


RZUT PARTERU - SEG. "C"



Numer	
0.01	
0.02	
0.03	
0.04	
0.05	
0.06	
0.07	
0.08	
0.09	
0.10	
0.11	
0.12	
0.13	
0.14	
0.15	
0.16	
0.17	
0.18	
0.19	
0.20	
0.21	
0.22	
0.23	
0.24	
0.25	
0.26	
0.27	
0.28	
0.29	
0.30	
0.31	
0.32	
0.33	
0.34	
0.35	
0.36	
0.37	
0.38	
0.39	
0.40	
0.41	
0.42	
0.43	
S	
Kut	